

BEFORE AND AFTER MINE SHAFT PICTURES JUNE 3<sup>rd</sup> 2009



BEFORE AND AFTER PICTURES: MINE SHAFT ENTRANCE ON MAY 29<sup>TH</sup> AND THE WORK DONE TILL JUNE 3<sup>RD</sup> 2009. THE WOOD HAS BEEN REPLACED. THE TOP RAFTERS HAVE BEEN INSTALLED AND THERE ARE NOW THERE ARE NOW 11 CROSS SUPPORT BEAMS INSTALLED. THE BEAM THAT WAS FALLING HAS BEEN REPLACED AND THE FLOOR HAS BEEN LEVELED.

